

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	1	"20020159724"	US- PGPUB; USPAT	2005/09/08 15:38
2	BRS	L2	0	1 and arc	US- PGPUB; USPAT	2005/09/08 15:38
3	BRS	L3	0	1 and (electrod\$4 same (electric\$3 char\$4\$4))	US- PGPUB; USPAT	2005/09/08 15:39
4	BRS	L4	1	1 and (electrod\$4)	US- PGPUB; USPAT	2005/09/08 15:39
5	BRS	L6	1	5 and arc	US- PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 15:45
6	BRS	L7	1	5 and (low profil\$4)	US- PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 16:07
7	BRS	L8	4	"6614975".pn.	US- PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 16:08
8	BRS	L9	1	8 and intensit\$4	US- PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 16:20

	Comments	Error Definition	Errors
1			
2			
3			
4			
5			
6			
7			
8			

	Type	L #	Hits	Search Text	DBs	Time Stamp
9	BRS	L10	1	5 and (MULTIPLY\$4 fold\$4)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/09/08 17:42
10	BRS	L11	1	5 and (common same direct\$5 same fiber\$2)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/09/08 17:43
11	BRS	L12	1	5 and (common near12 (axi\$4 direct\$5) near12 fiber\$2)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/09/08 17:44
12	BRS	L13	7	("20020159724" "5561728" "5013345" "6206583" "6046798" "5904413" "5611015") .pn.	US- PGPUB; USPAT	2005/09/08 18:23
13	BRS	L14	2	13 and actuat\$5	US- PGPUB; USPAT	2005/09/08 18:32
14	BRS	L15	1	"6046798" .pn.	US- PGPUB; USPAT	2005/09/08 18:32
15	BRS	L16	851495	(imag\$5 same (illumin\$5 detect\$5 display\$5))	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/09/08 18:33

	Comments	Error Definition	Errors
9			
10			
11			
12			
13			
14			
15			

	Type	L #	Hits	Search Text	DBs	Time Stamp
16	BRS	L17	360000	(rotat\$4 same (align\$5 fiber\$1 fibre\$1))	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/09/08 18:33
17	BRS	L18	1635	(electrodes (electric\$4 near7 arc\$1)) same (fus\$5 splic\$4 weld\$4) same (fiber\$1 fibre\$1)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/09/08 18:33
18	BRS	L19	3596	(fus\$5 splic\$4 weld\$4) near12 (fiber\$1 fibre\$1) same align\$5	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/09/08 18:33
19	BRS	L20	63416	(fiber\$1 fibre\$1) same imag\$4	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/09/08 18:33
20	BRS	L21	29	L16 and L17 and L18 and L19 and L20	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2005/09/08 18:33

	Comments	Error Definition	Errors
16			
17			
18			
19			
20			

	Type	L #	Hits	Search Text	DBs	Time Stamp
21	BRS	L22	23	L21 and (display\$4 screen\$3)	US- PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 18:33
22	BRS	L23	16	L22 and (motor\$1 actuat\$5) near12 (driv\$5 fiber\$1 fibre\$1)	US- PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 18:33
23	BRS	L24	20465	(imag\$5 same (illumin\$5 detect\$5 display\$5) same (fiber\$1 fibre\$1))	US- PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 18:33
24	BRS	L25	16	L23 and L24	US- PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 18:33
25	BRS	L27	7	L26 and L25	US- PGPUB; USPAT	2005/09/08 18:34
26	BRS	L28	1	15 and 27	US- PGPUB; USPAT	2005/09/08 18:34

	Comments	Error Definition	Errors
21			
22			
23			
24			
25			
26			

	Type	L #	Hits	Search Text	DBs	Time Stamp
27	BRS	L5	1	10/806838	US - PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 18:35
28	BRS	L26	7	("20020159724" "5561728" "5013345" "6206583" "6046798" "5904413" "5611015") .pn.	US - PGPUB; USPAT	2005/09/08 19:19

	Comments	Error Definition	Errors
27			
28			

	Type	Hits	Search Text
1	BRS	1	10/806533
2	BRS	1	10/806838
3	BRS	1	10/806538
4	BRS	1	10/806838
5	BRS	1	10/806838
6	BRS	1	S5 and (clamp\$4 same (posit\$5 adjust\$5) same (motion\$4 mov\$6 dimention\$4 coax\$5 abut\$5))
7	BRS	1	S5 and (motion\$4 near12 mov\$6 same (dimention\$4 coax\$5) same (align\$5 abut\$5))
8	BRS	1	S5 and (motion\$4 near12 mov\$6) and (mov\$6 same (dimention\$4 coax\$5) same (align\$5 abut\$5))
9	BRS	1	S5 and (imag\$5 same (illumin\$5 detect\$5 noncoinciden\$5 coincident\$4 display\$5))
10	BRS	850677	(imag\$5 same (illumin\$5 detect\$5 display\$5))
11	BRS	1	S5 and (rotat\$4 same (align\$5 fiber\$1 fibre\$1))
12	BRS	359756	(rotat\$4 same (align\$5 fiber\$1 fibre\$1))
13	BRS	1	S5 and (electrodes (electric\$4 near7 arc\$1)) same (fus\$5 splic\$4 weld\$4) same (fiber\$1 fibre\$1)
14	BRS	1632	(electrodes (electric\$4 near7 arc\$1)) same (fus\$5 splic\$4 weld\$4) same (fiber\$1 fibre\$1)
15	BRS	3595	(fus\$5 splic\$4 weld\$4) near12 (fiber\$1 fibre\$1) same align\$5
16	BRS	63344	(fiber\$1 fibre\$1) same imag\$4
17	BRS	29	S10 and S12 and S14 and S16 and S17
18	BRS	23	S18 and (display\$4 screen\$3)
19	BRS	1	S5 and (motor\$1 actuat\$5) near12 (driv\$5 fiber\$1 fibre\$1)

	DBs	Time Stamp	Comments	Error Definition
1	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 14:20		
2	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 15:00		
3	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 12:49		
4	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 17:14		
5	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 15:43		
6	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 17:48		
7	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 17:51		
8	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:38		
9	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:38		
10	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:55		
11	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:41		
12	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:41		
13	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:43		
14	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:44		
15	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:45		
16	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:45		
17	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:51		
18	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:53		
19	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:54		

	Errors	Ref #
1		S1
2		S2
3		S3
4		S4
5		S5
6		S6
7		S7
8		S8
9		S9
10		S10
11		S11
12		S12
13		S13
14		S14
15		S16
16		S17
17		S18
18		S19
19		S20

	Type	Hits	Search Text
20	BRS	16	S19 and (motor\$1 actuat\$5) near12 (driv\$5 fiber\$1 fibre\$1)
21	BRS	20440	(imag\$5 same (illumin\$5 detect\$5 display\$5) same (fiber\$1 fibre\$1))
22	BRS	16	S21 and S22
23	BRS	12	S23 and (imag\$5 same (screen\$3 display\$4))
24	BRS	851495	(imag\$5 same (illumin\$5 detect\$5 display\$5))
25	BRS	360000	(rotat\$4 same (align\$5 fiber\$1 fibre\$1))
26	BRS	1635	(electrodes (electric\$4 near7 arc\$1)) same (fus\$5 splic\$4 weld\$4) same (fiber\$1 fibre\$1)
27	BRS	3596	(fus\$5 splic\$4 weld\$4) near12 (fiber\$1 fibre\$1) same align\$5
28	BRS	63416	(fiber\$1 fibre\$1) same imag\$4
29	BRS	29	S25 and S26 and S27 and S28 and S29
30	BRS	23	S30 and (display\$4 screen\$3)
31	BRS	16	S31 and (motor\$1 actuat\$5) near12 (driv\$5 fiber\$1 fibre\$1)
32	BRS	20465	(imag\$5 same (illumin\$5 detect\$5 display\$5) same (fiber\$1 fibre\$1))
33	BRS	12	S34 and (imag\$5 same (screen\$3 display\$4))
34	BRS	0	S35 and sllid\$4
35	BRS	7	S35 and slid\$4
36	BRS	7	S35 and slid\$6
37	BRS	7	S38 and (motor\$3 actuat\$4 head\$3)
38	BRS	7	S38 and (motor\$4 actuat\$4 head\$3)
39	BRS	1	S43 and head
40	BRS	1	S43 and (lens\$2 head\$4)

	DBs	Time Stamp	Comments	Error Definition
20	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:54		
21	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:56		
22	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/06 18:55		
23	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:37		
24	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:37		
25	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:37		
26	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:37		
27	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:37		
28	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:37		
29	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:37		
30	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:37		
31	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:37		
32	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:37		
33	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 14:32		
34	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:44		
35	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:44		
36	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:44		
37	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:45		
38	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:45		
39	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:50		
40	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:50		

	Errors	Ref #
20		S21
21		S22
22		S23
23		S24
24		S25
25		S26
26		S27
27		S28
28		S29
29		S30
30		S31
31		S32
32		S33
33		S35
34		S36
35		S37
36		S38
37		S39
38		S40
39		S44
40		S45

	Type	Hits	Search Text
41	BRS	5	S41 and (lens\$2 head\$4)
42	BRS	7	S40 and clamp\$4
43	BRS	3	S41 and head\$3
44	BRS	5	S41 and (cover\$1 (clos\$4 near7 open\$5))
45	BRS	5	S41 and (cover\$4 (clos\$4 near7 open\$5))
46	BRS	16	S32 and S33
47	BRS	14	("20020159724" "5561728" "5013345" "6206583" "6046798" "5904413" "5611015") .pn.
48	BRS	7	("20020159724" "5561728" "5013345" "6206583" "6046798" "5904413" "5611015") .pn.
49	BRS	12	S31 and S35
50	BRS	7	S50 and S34
51	BRS	2	S52 and actuat\$5
52	BRS	1	"6206583" .pn.
53	BRS	1	10/806838
54	BRS	3	S25 and S42
55	BRS	0	S54 and S42
56	BRS	1	S54 and S52
57	BRS	1	S54 and (ax\$4 direct\$4 rotat\$5)
58	BRS	1	S54 and (ax\$4 direct\$4 rotat\$5 up\$4 low\$4 down)
59	BRS	0	"2000159724"
60	BRS	1	"20020159724"

	DBs	Time Stamp	Comments	Error Definition
41	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:51		
42	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:54		
43	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:52		
44	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:53		
45	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:53		
46	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:55		
47	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 10:57		
48	US-PGPUB; USPAT	2005/09/08 18:23		
49	US-PGPUB; USPAT	2005/09/08 10:58		
50	US-PGPUB; USPAT	2005/09/08 18:33		
51	US-PGPUB; USPAT	2005/09/08 12:41		
52	US-PGPUB; USPAT	2005/09/08 13:40		
53	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 13:19		
54	US-PGPUB; USPAT	2005/09/08 13:26		
55	US-PGPUB; USPAT	2005/09/08 13:27		
56	US-PGPUB; USPAT	2005/09/08 13:27		
57	US-PGPUB; USPAT	2005/09/08 13:41		
58	US-PGPUB; USPAT	2005/09/08 14:00		
59	US-PGPUB; USPAT	2005/09/08 14:00		
60	US-PGPUB; USPAT	2005/09/08 15:38		

	Errors	Ref #
41		S46
42		S41
43		S42
44		S47
45		S48
46		S34
47		S49
48		S50
49		S51
50		S52
51		S53
52		S54
53		S43
54		S55
55		S56
56		S57
57		S58
58		S59
59		S60
60		S61

	Type	Hits	Search Text
61	BRS	1	S61 and (dimens\$4 ax\$4 direct\$4 rotat\$5 up\$4 low\$4 down)
62	BRS	1	S61 and (imag\$4 same detect\$5)
63	BRS	1	S43 and (noncoincid\$5 coincident\$5)
64	BRS	1	S61 and (electr\$5 same (imag\$4 display\$4)) and display\$4
65	BRS	1	S61 and ((circui\$4 electr\$5) same (imag\$4 display\$4)) and display\$4
66	BRS	1	S61 and ((circui\$4 electr\$5) and (imag\$4 display\$4))
67	BRS	1	S61 and ((circ\$6 electr\$5) and (imag\$4 display\$4))
68	BRS	1	S61 and ((circ\$6 electr\$5 processc\$5 comput\$4) and (imag\$4 display\$4))
69	BRS	1	S61 and ((circ\$6 electr\$5 processc\$5 comput\$4) same (imag\$4 display\$4))

	DBs	Time Stamp	Comments	Error Definition
61	US-PGPUB; USPAT	2005/09/08 14:26		
62	US-PGPUB; USPAT	2005/09/08 14:26		
63	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 14:39		
64	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 14:40		
65	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 14:42		
66	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 14:42		
67	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 14:43		
68	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 14:44		
69	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/09/08 14:44		

	Errors	Ref #
61		S62
62		S63
63		S64
64		S65
65		S66
66		S67
67		S68
68		S69
69		S70